

REPAIR A BLADDER

PUNCHED HOLE: 1. Find the hole by inflating the bladder and plunge it in a bucket of water. 2. Mark the hole, deflate the bladder and allow it to dry properly. 3. Put a drop of Bladder glue. Allow drying for 15mn. *Kits: Big rescue Kit, Complete bladder Kit or Bladder glue.*



SMALL HOLE: 1. Clean the bladder with some alcohol. 2. Take a prepared patch, and apply on the hole. 3. If you use Blenderm, cut a piece at the required size, cut the edge in a round shape. *Kits: Big Rescue Kit, Small rescue kit, Complete bladder Kit, Multipatchs bladder Kit or Kit roll of Blenderm.*



TEAR: 1. Check that the cut is clean and don't make any crease. If needed cut slightly the edge to make them clean. 2. Clean properly the bladder with some alcohol. 3. Apply the patch or the Blenderm with rounded edge. *Kits: Big Rescue Kit, Small rescue kit, Complete bladder Kit, Multipatchs bladder Kit, or Kit roll of blenderm*



HERNIA: 1. Cut the bladder around the hernia and get a clean edge. Clean properly with some alcohol. 2. Place inside the bladder a patch PU simple. 3. Apply on top of it a patch of Blenderm self-adhesive.. *Kits: Big Rescue Kit, Small rescue kit, Complete bladder Kit or Multipatchs bladder Kit.*

